

VEHICLE INSPECTION REPORT

DE68BWV

Man TGL 8.190

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	10/12/2018	Colour	BLUE	Gearbox	AUTOMATIC
Year	2018	VIN	WMAN03ZZ3KY385845	Axle Combi	4x2
Mileage	326,661 Km Warranted	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	DIESEL	Cab Type	LX CAB	Rear Doors	Barn

LANE KEEP ASSIST, ADVANCED EMERGENCY BRAKING

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: A Post os
Scratched
UpTo 25mm Thru Paint



2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Other
N/A
N/A



7: Other
N/A
N/A



8: Other
N/A
N/A



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Handle Inner osf
Damaged
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault