

VEHICLE INSPECTION REPORT

WJ65YVP

Isuzu D-Max 2.5 TD TURBO

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 26/11/2015

Year 2015

Mileage 150,071 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN MPATFS86JFT010745

Body Style Pickup Double Cab

MOT Due 10/07/2026

Gearbox MANUAL

Gears 6

Axle Combi 4x4

CANNOT OPEN REAR DOOR TOW BAR

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- USB/iPod interface
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Boot Lid
Scratched
Over 25mm Thru Paint



2: Door osf
Chipped
Edge Chip



3: Wing osf
Dented
With Paint Damage



4: Door Mirror Assy osf
Broken
Replace



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Wing nsf
Scratched
Rusted



7: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK