

VEHICLE INSPECTION REPORT

LR16YCE

Vauxhall Combo 2000 1.3 CDTI 16V

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 28/04/2016

Year 2016

Mileage 136,895 Miles
Warranted

Fuel Type Diesel

Colour White

VIN W0L6ZYC1AG9579136

Body Style Panel Van L1

MOT Due 07/02/2026

CAP Clean £1,000.00

CAP Average £840.00

CAP Below £620.00

Gearbox MANUAL

SIDE LOAD DOOR, DEADLOCKS (WITH KEYS)

Tyres

NSF

NSR

OSF

OSR



Spare


Features

- Radio/CD
- Cloth seat trim
- Front electric windows
- Drivers airbag
- Central locking


Photos







Condition Check



Damage Photos



1: Moulding nsf Wing
Scratched (Painted)
Over 25mm Not Thru Paint



2: Moulding nsf Wing
Scuffed (Unpainted)
Over 100mm



3: Door nsf
Chipped
Multiple Chips



4: Panel Front
Chipped
Multiple Chips



5: Panel Rear
Scratched
Over 25mm Not Thru Paint



6: Panel Rear
Scratched
Over 25mm Not Thru Paint



7: Panel Rear
Scratched
Over 25mm Not Thru Paint



8: Fuel Flap
Scratched
Over 25mm Not Thru Paint




9: Door osf
Dented
With Paint Damage



10: Door osf
Scratched
Over 25mm Not Thru Paint



11: Wing osf
Dented
With Paint Damage



12: Wing osf
Chipped
Edge Chip



13: Bonnet
Scratched
UpTo 25mm Thru Paint



14: Bonnet
Scratched
Over 25mm Thru Paint



15: Bonnet
 Scratched
 UpTo 25mm Thru Paint



16: Bonnet
 Scratched
 UpTo 25mm Thru Paint



17: Door osf
 Chipped
 Edge Chip



18: Seat Base Cover nsf
 Soiled
 Light

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No