

VEHICLE INSPECTION REPORT

VN18UZU

VOLKSWAGEN AMAROK HIGHLINE 3.0 TDI V6 224PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 27/06/2018

Year 2018

Mileage 133,563 Miles Not Warranted

Fuel Type Diesel

Colour BLACK

VIN WV1ZZZ2HZJH024458

Body Style Pickup Double Cab

MOT Due 29/11/2025

CAP Clean £12,700.00

CAP Average £10,900.00

CAP Below £8,525.00

Gearbox AUTOMATIC

Gears 8

Axle Combi 4x4

E/MIRRORS

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Bumper Front
Chipped
Multiple Chips



5: Other
N/A
N/A



6: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Not Thru Paint



8: Qtr Panel Arch Extension os
Scratched (Painted)
UpTo 25mm Not Thru Paint



9: Door osf
Chipped
1 To 5



10: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Not Thru Paint

Interior

| | | | |
|--------------------------|----|--|----|
| Carpet Condition | OK | Upholstery Condition | OK |
| Seat Condition | OK | Odour | No |
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |