

VEHICLE INSPECTION REPORT

YK69MGY

Volvo FH 500

Inspection

| Serious Damage? | No | VAT | Plus VAT | | |
|-----------------|-----------------------------|------------|-------------------|-----------------|----------|
| | | V5 | Present | | |
| Details | | | | | |
| Reg. date | 17/01/2020 | VIN | YV2RT40C5KB914970 | Axle Combi | 6x2 |
| Year | 2020 | Body Style | Tractor Unit | Steering Combi | Mid-Lift |
| Mileage | 691,867 Km Not Warranted | MOT Due | 31/01/2026 | Rear Suspension | Air |
| | | Cab Type | GLOBETROTTER | | |
| Fuel Type | Diesel | | CAB | | |
| Colour | WHITE | Gearbox | AUTOMATIC | | |

WATER IN FUEL FILTER TWIN FUEL TANKS, SLIDING 5TH WHEEL

Vehicle

Tyres

| NSF | NSI1 | NSI2 | NSI3 | NSI4 | |
|-------|------|------|------|------|--|
| OSF | OSI1 | OSI2 | OSI3 | OSI4 | |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 | |
| | OS01 | OSO2 | OS03 | OSO4 | |

Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Navigation system
- · Front electric windows
- Park assist camera
- · Drivers airbag

Photos




















Condition Check



Damage Photos



1: Bonnet Dented With Paint Damage



2: Bonnet Chipped Multiple Chips



3: Bumper Front Scratched Over 100mm Thru Paint



4: Door Mirror Assy nsf Broken Replace



5: Door osf Chipped Multiple Chips

No Image

6: Seat Base Cover osf Torn Over 3mm

No Image

7: Dash Warning Lights Displayed No Action

Interior

| Seat Condition | Poor | | Odour - | |
|-----------------------|------|----|-----------------------|----|
| Engine Runs | | OK | No Excessive Smoking | OK |
| EML light illuminated | | OK | DPF light illuminated | OK |
| ABS light illuminated | | OK | | |