

# **VEHICLE INSPECTION REPORT**

**Vehicle** 

PE17HPN

### Daf CF 440

Inspection

Serious Damage?	No	VAT	Plus VAT		
		V5	To Follow		
Details					
Reg. date	06/03/2017	VIN	XLRTGM4100G149783	Axle Combi	6x2
Year	2017	Body Style	Tractor Unit	Steering Combi	Mid-Lift Steer
Mileage	1,486,547 Km Warranted	MOT Due	30/11/2025	Rear Suspension	Air
		Cab Type	NORMAL SLEEPER		
Fuel Type	Diesel	,,	CAB		
Colour	RED	Gearbox	AUTOMATIC		

\*COLLECTED AS NON RUNNER, TYRES AND SPRINGS NEED ATTENTION., INPUT ERROR ON MILEAGE HISTORY, MOT HISTORY INCORRECTLY RECORDED IN MILES/KM\*

#### **Tyres**

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OS03	OSO4	

#### **Features**

- Cruise controlCentral locking
- Radio/CDCloth seat trim
- Air conditioning
- · Front electric windows

#### **Photos**

















### **Condition Check**



## **Damage Photos**



1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched Over 100mm Thru Paint



3: Bumper Front Dented With Paint Damage



4: Bumper Front Dented With Paint Damage



5: Door nsf Scratched Over 25mm Thru Paint



6: Qtr Panel nsr Scratched Over 25mm Thru Paint



7: Qtr Panel Moulding ns Missing Replace



8: Qtr Panel Moulding ns Missing Replace



9: Qtr Panel Moulding os Missing Replace



10: Qtr Panel Moulding os Missing Replace



11: Door osf Scratched Over 25mm Thru Paint



12: Screen Front Chipped Over 10mm



13: Seat Base Cover osf Torn Over 3mm

#### Interior

Carpet Condition Seat Condition

OK Poor Upholstery Condition Odour

OK