

# VEHICLE INSPECTION REPORT

**LM66ZZH**

## Mercedes-Benz Sprinter 314 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 06/12/2016

Year 2016

Mileage 121,447 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9061332N689485

Body Style Tipper

MOT Due 03/11/2025

CAP Clean £4,800.00

CAP Average £4,000.00

CAP Below £2,950.00

Gearbox MANUAL

AD-BLUE, TOW BAR

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Front electric windows
- Central locking

## Condition Check



## Damage Photos



1: Bumper Front  
Dented  
Over 30mm



2: Bonnet  
Chipped  
Multiple Chips

No Image



4: Wing nsf  
Dented  
Over 30mm



5: Wing nsf  
Chipped  
Multiple Chips



6: Door nsf  
Dented  
With Paint Damage



7: Door nsf  
Chipped  
Multiple Chips



8: B Post os  
Scratched  
Over 25mm Thru Paint





9: B Post osf  
Dented  
Over 30mm



10: Door osf  
Dented  
With Paint Damage



11: Door osf  
Scratched  
Over 25mm Thru Paint



12: Door osf  
Chipped  
Multiple Chips



13: Seat Base Cover osf  
Holed  
Over 3mm



14: Screen Front  
Cracked  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

OK  
Poor

**Upholstery Condition**  
**Odour**

OK  
No