

VEHICLE INSPECTION REPORT

PE65UZD

Daf LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	16/10/2015	VIN	XLRAEL3700L448239	Gearbox	AUTOMATIC
Year	2015	Body Style	Box Van	Axle Combi	4x2
Mileage	769,963 Km Warranted	Service history	Yes	Tail Lift	Cantilever
Fuel Type	Diesel	MOT Due	31/07/2026		
Colour	RED	Cab Type	DAY CAB		

COLLECTED AS NON RUNNER- MECHANICAL W/O

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Other
N/A
N/A



4: Bumper Front
Chipped
Multiple Chips



5: Other
N/A
N/A



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Other
N/A
N/A



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Bumper Rear
Rusted
Over 5mm



11: Other
N/A
N/A



12: Other
N/A
N/A



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



14: Other
N/A
N/A



15: Door osf
 Scratched
 UpTo 25mm Thru Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	