

VEHICLE INSPECTION REPORT

BL70CVN

Nissan E-Nv200 80kW Acenta Van Auto 40kWh

| Inspection | | Vehicle | | | |
|-----------------|---------------------------|-------------|-------------------|-----------|-----------|
| Serious Damage? | No | VAT | Plus VAT | | |
| | | V5 | Buyer To Apply | | |
| Details | | | | | |
| Reg. date | 30/11/2020 | VIN | VSKYAAME0U0623767 | CAP Below | £3,475.00 |
| Year | 2020 | Body Style | Panel Van SWB | Gearbox | AUTOMATIC |
| Mileage | 24,301 Miles Warranted | MOT Due | 29/11/2025 | Gears | 1 |
| | | CAP Clean | £4,750.00 | | |
| Fuel Type | Electric | CAP Average | £4,250.00 | | |
| Colour | WHITE | | · | | |

TWIN SIDE LOAD DOORS, RACKING IN REAR, E/MIRRORS, V5 REF NUMBER AVAILABLE

| Tyres | | | |
|--------------|--|--|--|
| Tyres NSF | | | |
| NSR | | | |
| OSF | | | |
| OSR | | | |
| Spare | | | |

Features

- · Bluetooth connection
- Radio/CD
- Passenger airbag
- Cruise control
- · Air conditioning
- Central locking
- · Rear parking sensor
- Front electric windows
- Cloth seat trim
- · Digital radio
- Drivers airbag

Photos





















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Qtr Panel nsr Scratched Over 25mm Thru Paint



3: Qtr Panel Moulding ns Scuffed (Unpainted) Over 100mm



4: Lamp osr Broken Replace



5: Qtr Panel osr Dented With Paint Damage



6: Qtr Panel osr Dented With Paint Damage



7: Door osf Dented Over 30mm



8: Sill os Dented Over 30mm



9: Screen Front Scratched Over 30mm



10: Seat Base Cover nsf Soiled Heavy



11: Dash Warning Lights Displayed No Action

Interior

 Carpet Condition
 OK
 Upholstery Condition
 OK

 Seat Condition
 Poor
 Odour
 No

 EML light illuminated
 OK
 DPF light illuminated
 OK

 ABS light illuminated
 OK