

# **VEHICLE INSPECTION REPORT**

**WX17KFP** 

## Isuzu D-Max 2.5 TD

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	20/05/2017	VIN	MPATFS86JFT031372	<b>CAP Below</b>	£4,250.00
Year	2017	Body Style	Pickup Single Cab	Cab Type	CREW CAB
Mileage	81,950 Miles Warranted	MOT Due	31/03/2026	Gearbox	MANUAL
		CAP Clean	£6,600.00	Gears	6
Fuel Type	Diesel	CAP Average	£5,600.00	Axle Combi	4x4
Colour	WHITE				

#### WINCH, TOW BAR, ROOF RACK, POWER INVERTER

Tyr	es
-----	----

NSF

NSR

**OSF** 

OSR

Spare

### **Features**

- Park assist cameraDrivers airbag
- Digital radio
- Passenger airbag
- Air conditioningCentral locking
- Front electric windows
- Cloth seat trim

#### **Photos**

















# **Condition Check**



## **Damage Photos**



1: Bonnet Chipped Multiple Chips



2: Wing osf Scratched Over 25mm Thru Paint



3: Sill os Dented Over 30mm



4: Sill os Dented With Paint Damage



5: Qtr Panel osr Scratched Over 25mm Thru Paint



6: Qtr Panel osr Scratched Over 25mm Thru Paint



7: Panel Rear Chipped Multiple Chips



8: Qtr Panel nsr Scratched Over 25mm Thru Paint



9: Qtr Panel nsr Chipped Multiple Chips



10: Sill ns Dented Over 30mm



11: Sill ns Dented Over 30mm



12: Bumper Front Scratched Over 100mm Thru Paint



13: Door Pad osf Broken Replace



14: Fascia Panel Broken Replace



15: Fascia Panel Holed Over 3mm

### Interior

Carpet Condition Seat Condition	OK OK	Uphols Odour	stery Condition	Poor No	
Engine Runs		OK No E	xcessive Smoking		OK
EML light illuminated		OK DPF	light illuminated		OK
ABS light illuminated		ОК			