

VEHICLE INSPECTION REPORT

WD65UCW

Isuzu D-Max 2.5 TD TURBO

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	07/12/2015	VIN	MPATFS86JFT016323	CAP Below	£2,975.00
Year	2015	Body Style	Pickup Double Cab	Gearbox	MANUAL
Mileage	113,534 Miles Warranted	MOT Due	16/10/2025	Gears	6
Fuel Type	Diesel	CAP Clean	£4,950.00	Axle Combi	4x4
Colour	WHITE	CAP Average	£4,075.00		

WARNING LIGHT ON DASH TOW BAR, ROOF RACK, POWER INVERTER, 240V SOCKETS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Roof
Chipped
Multiple Chips



4: Wing nsf
Dented
Over 30mm



5: Qtr Panel osr
Dented
With Paint Damage



6: Door osf
Dented
With Paint Damage



7: Wing osf
Dented
Over 30mm



8: Wing osf
Dented
Over 30mm



9: Screen Front
Cracked
Replace



10: Seat Base Cover osf
Burn
Over 3mm



11: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		