

VEHICLE INSPECTION REPORT

PO70YAX

Fiat Ducato 35 2.3 Multijet 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 21/09/2020

Year 2020

Mileage 117,560 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA25000002P14933

Body Style Dropside MWB

MOT Due Expired

CAP Clean £4,650.00

CAP Average £4,150.00

CAP Below £3,400.00

Gearbox MANUAL

Gears 6

Tail Lift Column

COLLECTED AS NON RUNNER-GEARBOX ISSUES E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Bonnet
Dented
With Paint Damage



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: A Post ns
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Flasher Side Repeater ns
Broken
Replace



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Door nsf
Dented
2 Or Less UpTo 10mm



11: Sill ns
Dented
With Paint Damage



12: Other
N/A
N/A



13: Other
N/A
N/A



14: Door osf
Scratched
Over 25mm Thru Paint



15: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



16: Door osf
Dented
2 Or Less UpTo 10mm



17: Other
N/A
N/A



18: Seat Base Cover osf
Holed
Over 3mm



19: Other
N/A
N/A

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK