

VEHICLE INSPECTION REPORT

2635100

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 N/A

Details

Reg. date 01/01/2015

Year 2015

Mileage 50,475 Km Warranted

Fuel Type

Colour white

VIN ZCFA675B602635100

Body Style Box Van

MOT Due 31/08/2026

Cab Type DAY CAB

Axle Combi 4x2

Rear Doors Roller

Tail Lift Column

MOD654 FORM T/F, SINGLE SIDE ROLLER DOOR

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Bonnet
Scratched
UpTo 25mm Not Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Not Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Door Mirror Assy nsf
Missing
Replace



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Other
N/A
N/A



8: Other
N/A
N/A



9: Door nsf
 Scratched
 UpTo 25mm Thru Paint



10: Other
 N/A
 N/A



11: Bumper Rear
 Rusted
 Over 5mm



12: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint



13: Other
 N/A
 N/A



14: Door Mirror Assy osf
 Scuffed (Unpainted)
 UpTo 100mm



15: Door osf
Chipped
Edge Chip



16: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	