

VEHICLE INSPECTION REPORT

PF16UAA

Daf CF 460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 11/07/2016

VIN XLRTGM4300G114569

Axle Combi 6x2

Year 2016

Body Style Tractor Unit

Steering Combi Mid-Lif Steert

Mileage 419,125 Km Warranted

MOT Due 31/07/2025

Rear Suspension Air

Fuel Type Diesel

Cab Type SLEEPER CAB

Colour WHITE

Gearbox AUTOMATIC

SLIDING 5TH WHEEL


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Air conditioning
- Cloth seat trim
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Door Mirror Assy nsf
Missing
Replace



3: Qtr Panel nsr
Cracked
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average -
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK