

VEHICLE INSPECTION REPORT

PF70UOS

Fiat Ducato 35 2.3 Multijet 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 11/02/2021

Year 2021

Mileage 94,397 Miles
Warranted

Fuel Type Diesel

Colour MULTI-COLOURED

VIN ZFA25000002P66219

Body Style Dropside MWB

MOT Due 10/02/2026

CAP Clean £5,275.00

CAP Average £4,775.00

CAP Below £4,025.00

Gearbox MANUAL

Gears 6

ENGINE NEEDS REPLACING, WARNING LIGHT ON DASH E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Headlamp os
Missing
Replace



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Bonnet
Scratched
Over 25mm Thru Paint



5: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Door osf
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



14: Other
N/A
N/A



15: Door osf
Chipped
Edge Chip



16: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	