

VEHICLE INSPECTION REPORT

FN70AYB

Daf LF 180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 08/09/2020

Year 2020

Mileage 296,765 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAEL1500L497029

Body Style Box Van

MOT Due 30/09/2025

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Doors Barn

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

NSI2

OSI2

NSO2

OSO1

NSI3

OSI3

NSO3

OSO2

NSI4



OSI4

NSO4


OSO3

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Not Thru Paint



2: Bumper Front Moulding
Scuffed (Unpainted)
Up To 100mm



3: Other
N/A
N/A



4: Screen Front
Chipped
Over 10mm



5: Door Mirror Assy nsf
Missing
Replace



6: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Fog Lamp Surround nsf
Scuffed (Unpainted)
UpTo 100mm



8: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



9: Door nsf
Scratched
Over 25mm Not Thru Paint



10: Flasher Side Repeater ns
Broken
Replace



11: Other
N/A
N/A



12: Other
N/A
N/A



13: Other
N/A
N/A



14: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



15: Door osf
Dented
With Paint Damage



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Seat Base Cover osf
Holed
Over 3mm



18: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK