

VEHICLE INSPECTION REPORT

BT68LVM

Iveco Eurocargo 120-210

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	05/12/2018	VIN	ZCFAG1EF202687272	Axle Combi	4x2
Year	2018	Body Style	Curtainside	Rear Suspension	Air
Mileage	282,367 Km Warranted	MOT Due	30/09/2026	Tail Lift	Cantilever
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	MANUAL		

WARNING LIGHT ON DASH WEIGH SYSTEM, SURROUND CAMERA SYSTEM

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Auxiliary input socket
- Drivers airbag
- Cruise control
- Digital radio
- Central locking
- Front parking sensor
- Air conditioning
- Cloth seat trim
- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Not Thru Paint



2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK