

# VEHICLE INSPECTION REPORT

**KX17MLV**

## Daf LF 230

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 12/04/2017

Year 2017

Mileage 365,425 Km Warranted

Fuel Type Diesel

Colour SILVER

VIN XLRAEL1700L461393

Body Style Refuse Collector

Cab Type DAY CAB

Axle Combi 4x2

\*WARNING LIGHTS ON DASH\*


### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Park assist camera
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Wing of  
Cracked  
Replace



2: Bumper Front Moulding  
Scratched (Painted)  
Up To 25mm Thru Paint





3: Bonnet  
Scratched  
Over 25mm Not Thru Paint



4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Fog Lamp Surround ns  
Scuffed (Unpainted)  
UpTo 100mm



6: Door Mirror Assy nsf  
Missing  
Replace



7: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



8: Other  
N/A  
N/A



9: Other  
N/A  
N/A



10: Other  
N/A  
N/A



11: Other  
N/A  
N/A



12: Other  
N/A  
N/A



13: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm



14: Door Mirror Assy osf  
Missing  
Replace





15: Other  
N/A  
N/A



16: Door osf  
Chipped  
Edge Chip

**Interior**

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	Fault		Service indicator light illuminated	OK	