

VEHICLE INSPECTION REPORT

SH71GHA

Fiat Doblo 1.6 Multijet 16V

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/12/2021

Year 2021

Mileage 71,352 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V52035

Body Style Dropside L2

MOT Due 30/12/2025

CAP Clean £6,925.00

CAP Average £6,325.00

CAP Below £5,300.00

Gearbox MANUAL

Gears 5

WARNING LIGHTS ON DASH AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Rear parking sensor
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Wing nsf
Dented
Over 30mm



3: Wing nsf
Dented
With Paint Damage



4: Door nsf
Chipped
Multiple Chips



5: Bumper Rear
Dented
With Paint Damage



6: Door Pad osf
Broken
Replace



7: Seat Base Cover osf
Torn
Over 3mm



8: Seat Base Cover nsf
Soiled
Heavy



9: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	Fault		