

VEHICLE INSPECTION REPORT

HK17XYF

Daf CF 330

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 19/07/2017

Year 2017

Mileage 429,765 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRATM4100G148536

Body Style Tipper Grab

MOT Due 30/09/2025

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 6x2

WARNING LIGHTS ON DASH CHARLTON BODY, EDBRO TIPPING GEAR, PALFINGER EPSILON M125L CRANE (YEAR 2017), SINGLE HUB REDUCTION


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Fog Lamp Surround os
Scratched (Painted)
UpTo 25mm Thru Paint



3: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Thru Paint



4: Screen Front
Chipped
Over 10mm



5: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Dented
With Paint Damage



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Other
N/A
N/A



11: Bumper Rear
Rusted
Over 5mm



12: Other
N/A
N/A



13: Other
N/A
N/A



14: Other
N/A
N/A



15: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average		Average	
Average		-	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK