

VEHICLE INSPECTION REPORT

Vehicle

JP66DAF

Daf XF 460

Inspection

| Serious Damage? | No | VAT | Plus VAT | | |
|-----------------|-----------------------------|------------|-------------------|-----------------|----------------|
| | | V5 | Present | | |
| Details | | | | | |
| Reg. date | 13/10/2016 | VIN | XLRTGH4300G126207 | Axle Combi | 6x2 |
| Year | 2016 | Body Style | Tractor Unit | Steering Combi | Mid-Lift Steer |
| Mileage | 935,935 Km Not Warranted | MOT Due | 31/12/2025 | Rear Suspension | Air |
| | | Cab Type | SUPER SPACE CAB | | |
| Fuel Type | Diesel | Gearbox | AUTOMATIC | | |
| Colour | SILVER | | | | |

SLIDING 5TH WHEEL

Tyres

| NSF | NSI1 | NSI2 | NSI3 | NSI4 | |
|-------|------|------|------|------|--|
| OSF | OSI1 | OSI2 | OSI3 | OSI4 | |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 | |
| | OS01 | OSO2 | OS03 | OSO4 | |

Features

- Bluetooth connectionRadio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Navigation systemFront electric windows
- Park assist camera
- Central locking

Photos
















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Panel Front Cracked Replace



3: Bumper Front Moulding Scratched (Painted) Over 25mm Thru Paint



4: Bumper Front Scratched Over 100mm Thru Paint



5: Door Moulding nsf Scratched (Painted) Over 25mm Thru Paint



6: Qtr Panel Moulding ns Scuffed (Unpainted) Over 100mm



7: Wing osf Chipped Multiple Chips



8: Door Mirror Assy osf Scratched (Painted) Over 25mm Thru Paint

Interior

| Carpet Condition | OK | Upho | olstery Condition OK | |
|-----------------------|----|---------|----------------------|----|
| Seat Condition | OK | Odou | ır - | |
| Engine Runs | | OK No I | Excessive Smoking | OK |
| EML light illuminated | | OK DPF | = light illuminated | OK |
| ABS light illuminated | | OK | | |