

VEHICLE INSPECTION REPORT

PL66YYF

Daf CF 460

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	06/02/2017	VIN	XLRTGM4300G137788	Axle Combi	6x2
Year	2017	Body Style	Tractor Unit	Steering Combi	Mid-Lif Steert
Mileage	358,402 Km Warranted	MOT Due	31/05/2025	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SLEEPER CAB		
Colour	WHITE/GREEN	Gearbox	AUTOMATIC		

WARNING LIGHT ON DASH SLIDING 5TH WHEEL

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	OSO4	

Features

- Cruise control
 Radio/CD
- · Drivers airbag
- Park assist camera
- Manual sunroof
- · Central locking
- Auxiliary input socketAir conditioning
- Cloth seat trim
- Digital radio
 Front electric windows

Photos




















Condition Check



Damage Photos



1: Seat Base Cover osf Soiled Light



2: Bumper Front Scratched Over 25mm Not Thru Paint

Interior

Carpet ConditionAverageSeat ConditionAverage

Upholstery Condition Average **Odour** -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK