

# **VEHICLE INSPECTION REPORT**

482,269 Km Warranted Body Style

Diesel

**Vehicle** 

**MOT Due** 

FN17BSZ

## **Daf LF 260**

Inspection

Serious Damage?	No	VAT	Plus VAT		
		V5	Present	-	
Details					
Reg. date	03/07/2017	Colour	WHITE	Cab Type	DAY CAB
Year	2017	VIN	XLRAEL3700L463853	Gearbox	AUTOMATIC

Curtainside

31/07/2026

#### **Tyres**

Mileage

**Fuel Type** 

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OSO1	OSO2	OSO3	OSO4	

### **Features**

Park assist camera

• Air conditioning

#### **Photos**







4x2

Barn

**Axle Combi** 


**Rear Doors** 








<sup>\*</sup>BROKEN CLUTCH, GEAR SELECTED MISSING, VEHICLE DOES DRIVE\* FORKLIFT BRACKETS, SURROUND CAMERA SYSTEM



# **Condition Check**



## **Damage Photos**



1: Screen Front Chipped UpTo 10mm



2: Bonnet Scratched UpTo 25mm Thru Paint



3: Door Mirror Assy nsf Scuffed (Unpainted) UpTo 100mm



4: Wing nsf Scratched UpTo 25mm Thru Paint



5: Bumper FrontScratched25 to 100mm Thru Paint



6: Other N/A N/A



7: Door Mirror Assy osf Scuffed (Unpainted) UpTo 100mm



8: Other N/A N/A



9: Seat Base Cover osf Torn Over 3mm



10: Other N/A N/A

### Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Average Odour -	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK