

VEHICLE INSPECTION REPORT

LN70XSK

Mercedes-Benz Antos

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	27/01/2021	VIN	WDB96302020382722	CAP Below	£10,950.00
Year	2021	Body Style	Curtainside	Cab Type	DAY CAB
Mileage	212,356 Km Warranted	MOT Due	28/02/2026	Gearbox	AUTOMATIC
Fuel Type	Diesel	CAP Clean	£12,100.00	Axle Combi	6x2
Colour	WHITE	CAP Average	£11,650.00	Rear Doors	Barn

WARNING LIGHT ON DASH FORKLIFT BRACKETS, SURROUND CAMERA SYSTEM


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Fog Lamp Surround os
Scuffed (Unpainted)
UpTo 100mm



3: Screen Front
Chipped
UpTo 10mm



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Fog Lamp Surround ns
Scuffed (Unpainted)
UpTo 100mm



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Other
N/A
N/A



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Bumper Rear
Rusted
Over 5mm



11: Other
N/A
N/A



12: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



13: Other
N/A
N/A



14: Air Vents nsf
Damaged
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK