

VEHICLE INSPECTION REPORT

PK69ZND

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/02/2020

Year 2020

Mileage 127,891 Miles
Warranted

Fuel Type Diesel

Colour RED

VIN W1V9071352N079991

Body Style Dropside

MOT Due 16/02/2026

Tail Lift Column

AD-BLUE, TOW BAR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Park assist camera
- Passenger airbag
- Digital radio
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint




4: Wing nsf
Dented
With Paint Damage
Over 25mm Thru Paint



5: Door Moulding nsf
Missing
Replace



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Chipped
Multiple Chips



8: Door nsf
Dented
With Paint Damage
Over 25mm Thru Paint



9: Door osf
Chipped
Multiple Chips



10: Door Mirror Assy osf
Broken
Replace



11: Bumper Front
Insecure
Action Required

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		No
Engine Runs	OK		No Excessive Smoking		OK
EML light illuminated	OK		DPF light illuminated		OK
ABS light illuminated	OK				