

VEHICLE INSPECTION REPORT

SF16CLD

Vauxhall Movano F3500 2.3 CDTI 136ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 27/07/2016

Year 2016

Mileage 47,915 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W0LMSP4Y2GB107456

Body Style Tipper Double Cab

MOT Due 19/03/2026

CAP Clean £5,975.00

CAP Average £5,000.00

CAP Below £3,700.00

Gearbox MANUAL

Gears 6

TOW BAR, E/MIRRORS.

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Bonnet
Dented
With Paint Damage



3: Wing osf
Dented
With Paint Damage



4: Door osf
Dented
With Paint Damage



5: Door osr
Dented
With Paint Damage



6: Qtr Panel osr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Sill ns
Dented
With Paint Damage



9: Door nsr
Dented
With Paint Damage



10: B Post ns
Dented
With Paint Damage



11: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows	OK	Radio	OK
		Steering	OK