

# **VEHICLE INSPECTION REPORT**

Vehicle

VAT

**CN69VXM** 

### **Mercedes-Benz Sprinter 314 CDI**

Fuel Type	Diesel					
	Warranted	MOT Due	Expired	Gearbox	MANUAL	
Mileage	146,708 Miles	Body Style	Panel Van MWB	CAP Below	£5,900.00	
Year	2019	VIN	WDB9106332P135149	CAP Average	£7,425.00	
Reg. date	24/09/2019	Colour	WHITE	CAP Clean	£8,425.00	
Details						
		<u>V5</u>	To Follow			

Plus VAT

AD BLUE, SIDE LOAD DOOR.

#### **Tyres**

Inspection

Serious Damage?

NSF

NSR

OSF

OSR

Spare

#### **Features**

• Radio/CD

• Front electric windows

· Central locking

#### **Photos**
















## **Condition Check**



### **Damage Photos**



1: Bonnet Dented Over 30mm



2: Bumper Front Moulding Broken Replace



3: Wing nsf Dented With Paint Damage



4: Door osf Dented Over 30mm



5: Qtr Panel osr Dented With Paint Damage



6: Bumper Rear Moulding Broken Replace



7: Qtr Panel nsr Dented With Paint Damage



8: Door nsr Dented Over 30mm

#### Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average No	
Engine Runs		OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Turbo Boosting		OK	Gearbox Static Gear Sel	ection (engine running)	OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illumina	ted	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	ıminated	OK
Windows		OK	Radio		OK
			Steering		OK