

VEHICLE INSPECTION REPORT

YT65TZH

Mercedes-Benz Antos 1824

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	02/10/2015	Body Style	Fridge Box	Axle Combi	4x2
Year	2015	Service history	Yes	Rear Suspension	Air
Mileage	646,587 Km Warranted	Service documents	Printout	Rear Doors	Roller
Fuel Type	Diesel	MOT Due	30/09/2025	Tail Lift	Column
Colour	WHITE	Cab Type	DAY CAB		
VIN	WDB9630032L983346	Gearbox	AUTOMATIC		

THERMOKING T1000R UNIT, STANDBY PLUG

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Radio/CD Multichanger
- Air conditioning
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos




1: Door nsf
Chipped
Edge Chip



2: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



3: Moulding onsf Wing
Broken
Replace



4: Panel Front
Hole
Over 10mm



5: Panel Rear
Hole
Over 10mm



6: Panel Front
Scratched
Over 25mm Not Thru Paint



7: Moulding nsf Wing
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	