

VEHICLE INSPECTION REPORT

SA71KKD

Fiat Doblo Work Up 16V II 1.6 MULTIJET

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 08/11/2021

Year 2021

Mileage 87,265 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V23623

Body Style Dropside L2

MOT Due 07/11/2025

CAP Clean £6,300.00

CAP Average £5,750.00

CAP Below £4,825.00

Gearbox MANUAL

Gears 5

WARNING LIGHT ON DASH AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Drivers airbag
- Radio/CD
- Passenger airbag
- Air conditioning
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Broken
Replace



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Door osf
Dented
Over 30mm



6: Wing osf
Dented
Over 30mm



7: Door Mirror Assy osf
Broken
Replace



8: Wing osf
Dented
Over 30mm



9: Fascia Panel
Missing
Replace




10: Carpets Front
Holed
Over 3mm



11: Seat Base Cover osf
Torn
Over 3mm



12: Seat Base Cover nsf
Soiled
Heavy



13: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		