

# VEHICLE INSPECTION REPORT

**PN71BVO**

## Fiat Doblo 16V II 1.6 MULTIJET

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 22/11/2021

Year 2021

Mileage 65,248 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V35173

Body Style Dropside L2

MOT Due 10/03/2026

CAP Clean £7,175.00

CAP Average £6,525.00

CAP Below £5,475.00

Gearbox MANUAL

Gears 5

AD-BLUE

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Radio/CD
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Door Mirror Assy nsf  
Broken  
Replace





3: Door nsf  
Scratched  
UpTo 25mm Thru Paint



4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: B Post ns  
Scratched  
Over 25mm Not Thru Paint



6: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



9: Sill os  
Dented  
With Paint Damage



10: Door osf  
Scratched  
Over 25mm Thru Paint



11: A Post os  
Dented  
With Paint Damage



12: Roof  
Dented  
Over 30% Of Panel



13: Door Moulding osf  
Broken  
Replace



14: Wing osf  
Scratched  
Over 25mm Thru Paint





15: Bumper Front  
Cracked  
Over 25mm



16: Door Pad osf  
Broken  
Replace



17: Switches And Controls  
Broken  
Replace



18: Fascia Panel  
Missing  
Replace



19: Carpets Front  
Holed  
Over 3mm



20: Seat Base Cover osf  
Torn  
Over 3mm



21: Seat Base Cover nsf  
Burn  
Over 3mm

Interior

Carpet Condition		Poor	Upholstery Condition		Poor
Seat Condition		Poor	Odour		Yes
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			