

VEHICLE INSPECTION REPORT

HX16FZK

Mercedes-Benz Antos 1824

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	20/05/2016	VIN	WDB96300320021304
Year	2016	Body Style	Flatbed & Crane
Mileage	366,573 Km Warranted	Service history	Full
Fuel Type	Diesel	MOT Due	Expired
Colour	WHITE	Cab Type	DAY CAB
		Gearbox	AUTOMATIC
		Axle Combi	4x2
		Rear Suspension	Air

PALFINGER PK 18002 EH REMOTE CRANE (YEAR 2015), SURROUND CAMERA SYSTEM, CRANE TEST IN OFFICE

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Radio/CD
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Auxiliary input socket
- Front electric windows
- Digital radio
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm

2: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK