

VEHICLE INSPECTION REPORT

• Air conditioning



Man TGS 26.330

| Inspection | | Vehicle | | | |
|-----------------|-----------------------|------------|------------------|-------------------------------|-------------|
| Conditions | Outdoors - Good light | VAT | Plus VAT | | |
| Serious Damage? | No | V5 | Present | | |
| Details | | | | | |
| Reg. date | 01/11/2021 | VIN | WMA19FZZ9NM89483 | 9 Doors | 2 |
| Year | 2021 | Body Style | Curtainside | Axle Combi | 6x2 |
| Mileage | 192,209 Km Warranted | Keys | 2 SLEEPER CAB | Rear Suspension Rear Doors | Air Barn |
| Fuel Type | Diesel | Cab Type | | | |
| Colour | RED | Gearbox | Automatic | _ | |
| Tyres | | | | | |
| NSF | NSI1 | NSI2 | NSI3 | | NSI4 |
| OSF | OSI1 | OSI2 | OSI3 | | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | | NSO4 |
| | OS01 | OSO2 | OSO3 | | OSO4 |

Features

Cruise control

Front electric windows


Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door Moulding osf Scuffed (Unpainted) Over 100mm

2: Bonnet Chipped Multiple Chips





3: Bumper Front Moulding Scuffed (Unpainted) Over 100mm

4: Qtr Panel osr Dented Over 30mm

Interior

| Carpet Condition Seat Condition | Average Average | | Upholstery Condition Odour | Average - | |
|------------------------------------|--------------------|----|-------------------------------|--------------|----|
| EML light illuminated | | OK | Oil warning light illumina | ated | OK |
| Airbag light illuminated O | | OK | DPF light illuminated | | OK |
| ABS light illuminated | | OK | Service indicator light ill | uminated | OK |