

VEHICLE INSPECTION REPORT

Vehicle

Gearbox

VAT

FN18PZT

Daf LF 230

Serious Damage?

Inspection

		V5	To Follow	-	
Details					
Reg. date	22/03/2018	VIN	XLRAEL3700L472432	Axle Combi	4x2
Year	2018	Body Style	Curtainside	Rear Suspension	Steel
Mileage	452,477 Km Warranted	MOT Due	30/11/2025	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Tuckaway

Plus VAT

AUTOMATIC

WARNING LIGHTS ON DASH SURROUND CAMERA SYSTEM

WHITE

Tyres

Colour

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	OSO4	

Features

Navigation system

• Park assist camera

Photos

















Condition Check



Damage Photos



1: Bumper Front Chipped Multiple Chips



2: Screen Front Chipped Over 10mm



3: Bonnet Chipped Multiple Chips



4: Bumper Front Scratched UpTo 25mm Thru Paint



5: Other N/A N/A



6: Other N/A N/A



7: Door nsr Scratched Over 25mm Thru Paint



8: Door nsr Dented Between 10mm + 30mm



9: Door osr Scratched Over 25mm Thru Paint



10: Other N/A N/A



11: Other N/A N/A



12: Seat Base Cover osf Holed Over 3mm

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Average Odour -	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		Fault	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running	OK
			No Excessive Smoking	OK
EML light illuminated		Fault	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK