Rear Suspension

Rear Doors

Air

Barn



VEHICLE INSPECTION REPORT

Vehicle

Service documents

MOT Due

VAT

FJ65VXY

DAF LF 250

Inspection

Serious Damage?

Mileage	578,122 Km Warranted	Service history	Yes	Axle Combi	4x2
Year	2015	Body Style	Curtainside	Gearbox	AUTOMATIC
Reg. date	17/12/2015	VIN	XLRAEL3700L447704	Cab Type	DAY CAB
Details					
		<u>V5</u>	Present	-	

Electronic / Online

30/04/2026

Plus VAT

\MADNING	LICHT	UN DVSH	AD BLUE	WEIGH SYSTEM

Diesel

WHITE

Tyres

Colour

Fuel Type

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	_
	OS01	OSO2	OSO3	OSO4	_

Features

Park assist camera

• Air conditioning

Photos



















Condition Check



Damage Photos



1: Wing osf Scratched Over 25mm Thru Paint



2: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



3: Other N/A N/A



4: Other N/A N/A



5: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



6: Screen Front Chipped Over 10mm



7: Other N/A N/A



8: Other N/A N/A



9: Other N/A N/A



10: Other N/A N/A



11: Other N/A N/A



12: Other N/A N/A



13: Door Mirror Assy osf Scuffed (Unpainted) UpTo 100mm



14: Door osf Scratched Over 25mm Not Thru Paint



15: Door osf Scratched UpTo 25mm Thru Paint



16: Seat Base Cover osf Holed Over 3mm

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average -	
Engine Runs		OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Parking Brake C		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		Fault	Oil warning light illumina	tod	OK
LIVIE light mummated		i auit	On warriing light liidriina	ieu	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	ıminated	OK