

VEHICLE INSPECTION REPORT

YN67YXU

Daf LF 150

	Vehicle				
No	VAT	Plus VAT			
	V5	Buyer To Apply	_		
07/11/2017	Colour	GREEN	Cab Type	DAY CAB	
2017	VIN	XLRAEL1500L46947	5 Gearbox	MANUAL	
Mileage 245,696 Km Not	Body Style	Dropside	Axle Combi	4x2	
Warranted	MOT Due	31/05/2026	Rear Suspension	Steel	
Diesel	_		_		
NSI1	NSI2	NSI3		NSI4	
OSI1	OSI2	OSI3		OSI4	
nre NSO1 NSO2	NSO2	NSO3		NSO4	
OS01	OS02	oso3		OSO4	
	07/11/2017 2017 245,696 Km Not Warranted Diesel NSI1 OSI1 NSO1	No VAT V5 V5 07/11/2017 Colour 2017 VIN 245,696 Km Not Warranted Body Style MOT Due MOT Due Diesel NSI1 OSI1 OSI2 NSO1 NSO2	No VAT Plus VAT V5 Buyer To Apply 07/11/2017 Colour GREEN 2017 VIN XLRAEL1500L469473 245,696 Km Not Warranted Body Style Dropside MOT Due 31/05/2026 NSI1 NSI2 NSI3 OSI1 OSI2 OSI3 NSO1 NSO2 NSO3	No VAT Plus VAT V5 Buyer To Apply 07/11/2017 Colour GREEN Cab Type 2017 VIN XLRAEL1500L469475 Gearbox 245,696 Km Not Warranted Body Style Dropside Axle Combi MOT Due 31/05/2026 Rear Suspension Diesel NSI1 NSI2 NSI3 OSI1 OSI2 OSI3 NSO1 NSO2 NSO3	

Features

- Cruise controlCentral locking
- Digital radioCloth seat trim
- Radio/CD

• Front electric windows

Photos





















Condition Check



Damage Photos



1: Door Mirror Assy osf Scuffed (Unpainted) Over 100mm



2: Door osf Dented With Paint Damage



3: Panel Front Scratched Over 25mm Thru Paint



4: Bumper Front Moulding Broken Replace



5: Door osf Scratched Over 25mm Thru Paint



6: Bumper Front Moulding Broken Replace



7: Bumper Front Scratched Over 100mm Thru Paint



8: Door Mirror Assy nsf Scuffed (Unpainted) Over 100mm



9: Lamp nsr Broken Replace



10: Door Pad osf Soiled Heavy



11: Seat Base Cover nsf Soiled Heavy

Interior

Carpet Condition Seat Condition	OK Poor		Upholstery Condition Odour	Poor -	
Engine Runs	1 001		No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			