

VEHICLE INSPECTION REPORT

WX66KWU

Isuzu D-Max 2.5 TD

Non	Runner

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	01/11/2016	VIN	MPATFS86JFT030443	CAP Below	£2,575.00
Year	2016	Body Style	Pickup Single Cab	Gearbox	MANUAL
Mileage	145,114 Miles Warranted	MOT Due	Expired	Gears	6
		CAP Clean	£4,175.00	Axle Combi	4x4
Fuel Type	Diesel	CAP Average	£3,500.00		
Colour	WHITE		,		

NON-RUNNER - STARTS AND DRIVES, NO CLUTCH TWIN SIDE LOAD DOOR, TOW BAR, ROOF RACK, POWER INVERTER, FUSE BOX, 240V SOCKETS

Tyres

NSF

NSR

OSF

OSR Spare

Features


- · Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioningCentral locking
- Front electric windows
- Cloth seat trim

Photos




















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched Over 100mm Thru Paint



3: Wing nsf Dented Over 30% Of Panel



4: Wing nsf Dented Over 30mm



5: Wing nsf Dented With Paint Damage



6: Qtr Panel nsr Scratched Over 25mm Thru Paint



7: Qtr Panel nsr Dented Over 30mm



8: Qtr Panel nsr Chipped Multiple Chips



9: Qtr Panel nsr Chipped Multiple Chips



10: Qtr Panel osr Scratched Over 25mm Thru Paint



11: Qtr Panel osr Dented Over 30mm



12: Door osf Dented With Paint Damage



13: Wing osf Dented Over 30mm



14: Bumper Front Scratched Over 100mm Thru Paint



15: Seat Base Cover osf Soiled Heavy



16: Dash Warning Lights Displayed No Action

Interior

Carpet Condition Seat Condition	OK Poor		Upholstery Condition Odour	OK No	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	uminated	Fault