

VEHICLE INSPECTION REPORT

CU64FKG

Ford Transit 350 2.2 TDCI 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	08/12/2014	VIN	WF0XXXTTGXEU33648	CAP Below	£1,100.00
Year	2014	Body Style	Panel Van L3	Gearbox	MANUAL
Mileage	184,039 Miles Warranted	MOT Due	05/11/2025	Gears	6
Fuel Type	Diesel	CAP Clean	£1,900.00		
Colour	WHITE	CAP Average	£1,525.00		

*WARNING LIGHT ON DASH *SIDE LOAD DOOR, ROOF RACK, HEATED WINDSCREEN, POWER INVERTER, 240V SOCKETS

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Roof
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage



4: Panel Front
Dented
Over 30mm



5: Bonnet
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Chipped
Multiple Chips



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Fuel Flap
Missing
Replace



10: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm



11: B Post ns
Dented
With Paint Damage



12: Roof
Dented
Over 30mm



13: Qtr Panel nsr
Dented
With Paint Damage



14: Qtr Panel nsr
Dented
With Paint Damage



15: Qtr Panel nsr
Dented
With Paint Damage



16: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



17: Qtr Panel nsr
Dented
With Paint Damage



18: Qtr Panel nsr
Dented
With Paint Damage



19: Qtr Panel Moulding ns
Missing
Replace



20: Qtr Panel nsr
Dented
Over 30mm



21: Qtr Panel Moulding ns
Missing
Replace



22: Roof
Dented
With Paint Damage



23: C Post ns
Scratched
Over 25mm Thru Paint



24: Qtr Panel nsr
Dented
With Paint Damage



25: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



26: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



27: Qtr Panel Trim ns
Missing
Replace



28: Qtr Panel nsr
Dented
With Paint Damage



29: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



30: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



31: Door nsr
Dented
With Paint Damage



32: Door nsr
Scratched
Over 25mm Thru Paint



33: Door nsr
Dented
Over 30mm



34: Door osr
Dented
With Paint Damage



35: Door osr
Dented
Over 30mm



36: Door Moulding osr
Scuffed (Unpainted)
Over 100mm



37: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



38: Qtr Panel osr
Dented
Over 30mm



39: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



40: Door Moulding osf
Scuffed (Unpainted)
Over 100mm




41: Door osf
Scratched
Over 25mm Thru Paint




42: Door Pad osf
Soiled
Heavy



43: Seat Base Cover osf
Torn
Over 3mm



44: Seat Base Cover nsf
Soiled
Heavy



45: Seat Base Cover nsf
Soiled
Heavy



46: Door Pad nsf
Soiled
Heavy



47: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	Fault	Service indicator light illuminated	Fault
ABS light illuminated	Fault		