

VEHICLE INSPECTION REPORT

FN70AYA

Daf CF 340

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/09/2020

VIN XLRASM4100G305664

Axle Combi 6x2

Year 2020

Body Style Box Van

Rear Suspension Air

Mileage 481,874 Km Warranted

MOT Due 30/09/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour WHITE

Gearbox AUTOMATIC

REAR LIFT AXLE

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Wing nsf
Poor Previous Repair
Rippled Up To 30%



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel Trim os
Scuffed
Over 25mm



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door osf
Scratched
Over 25mm Thru Paint



9: Seat Base Cover of
Burn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		