

VEHICLE INSPECTION REPORT

VN16PJJ

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 20/06/2016

Year 2016

Mileage 120,134 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN SEG2628HR6BG22441

Body Style Refuse Collector

MOT Due 31/03/2026

Cab Type CREW CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Rear Steer

Rear Suspension Air

WARNING LIGHT ON DASH OLYMPUS BODY TERBERG SPLIT LIFT, SURROUND CAMERA SYSTEM

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Park assist camera
- Cloth seat trim
- Digital radio
- Radio/CD


Photos







Condition Check



Damage Photos



1: Door osf
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Panel Front
Chipped
Multiple Chips



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		Fault	DPF light illuminated		Fault
ABS light illuminated		OK			