

VEHICLE INSPECTION REPORT

VN16PKO

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 11/07/2016

Year 2016

Mileage 115,603 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN SEG2628HR6BG22456

Body Style Refuse Collector

MOT Due 28/02/2026

Cab Type CREW CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Rear Steer

Rear Suspension Air

OLYMPUS 23W BODY, TERBERG SPLIT LIFT, SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

NSI2

OSI2

NSO2

OSO1

OSO2

NSI3

OSI3

NSO3

OSO3

NSI4

OSI4

NSO4

OSO4

Features


- Bluetooth connection
- Front electric windows
- Park assist camera
- Cloth seat trim
- Digital radio
- Radio/CD

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		