

VEHICLE INSPECTION REPORT

DA70WVL

Man TGS 26.330

Inspection

Conditions	Outdoors - Good light
Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	25/01/2021	VIN	WMA18SZZ6MM869486	Axle Combi	6x2
Year	2021	Body Style	Curtainside	Rear Suspension	Air
Mileage	478,443 Miles Warranted	Cab Type	SLEEPER CAB	Rear Doors	Barn
Fuel Type	Diesel	Gearbox	Automatic	Tail Lift	Tuckaway
Colour	RED	Doors	2		

Rear Lift


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Cruise control
- Park assist camera
- Air conditioning
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



2: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



3: Bonnet
Scratched
Over 25mm Not Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel osr
Dented
With Paint Damage



6: Tailgate
Rusted
Over 5mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	