

VEHICLE INSPECTION REPORT

Vehicle

PK67VFZ

Daf CF 450

Inspection

Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	09/11/2017	VIN	XLRTGM4100G181301	Axle Combi	6x2
Year	2017	Body Style	Tractor Unit	Steering Combi	Mid-Lift Steer
Mileage	1,120,705 Km Warranted	MOT Due	31/07/2026	Rear Suspension	Air
		Cab Type	SLEEPER CAB		
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	RED				

COLLECTED AS NON-RUNNER, REQUIRE ATT

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OSO1	OSO2	OSO3	OSO4	

Features

• Air conditioning

Photos

















Condition Check



Damage Photos



1: Wing osf Scratched Over 25mm Thru Paint



2: Fog Lamp Surround os Broken Replace



3: Bumper Front Chipped Multiple Chips



4: Bonnet Chipped Multiple Chips



5: Screen Front Chipped UpTo 10mm



6: Wing nsf Cracked Replace



7: Bumper Front Moulding Scratched (Painted) Over 25mm Thru Paint



8: Door Mirror Assy nsf Scuffed (Unpainted) UpTo 100mm



9: Other N/A N/A



10: Door nsf Scratched UpTo 25mm Thru Paint



11: B Post ns Scratched Over 25mm Not Thru Paint



12: Other N/A N/A



13: Door osf Chipped Over 5mm



14: Door osf Dented With Paint Damage



15: Door Mirror Assy osf Broken Replace



16: Other N/A N/A

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average -	
Engine Runs		OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illumina	ted	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated OK			Service indicator light illuminated		OK