

# VEHICLE INSPECTION REPORT

**PO70YBC**

## Fiat Ducato 35 2.3 MULTIJET 140PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 03/11/2020

Year 2020

Mileage 138,705 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA25000002P49084

Body Style Dropside

MOT Due 02/11/2025

CAP Clean £4,250.00

CAP Average £3,800.00

CAP Below £3,125.00

Gearbox MANUAL

Gears 6

Tail Lift Column

AD-BLUE, E/ MIRRORS, TOW BAR

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Wing nsf  
Dented  
With Paint Damage



3: Bumper Front  
Insecure  
Action Required



4: A Post ns  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Dented  
With Paint Damage



6: Door nsf  
Chipped  
Multiple Chips



7: Door osf  
Chipped  
Multiple Chips



8: Sill os  
Scratched  
Over 25mm Thru Paint



9: Seat Base Cover osf  
Torn  
Over 3mm



10: Seat Base Cover nsf  
Soiled  
Heavy

Interior

|                         |    |      |                             |    |    |
|-------------------------|----|------|-----------------------------|----|----|
| <b>Carpet Condition</b> |    | OK   | <b>Upholstery Condition</b> |    | OK |
| <b>Seat Condition</b>   |    | Poor | <b>Odour</b>                |    | No |
| Engine Runs             | OK |      | No Excessive Smoking        | OK |    |
| EML light illuminated   | OK |      | DPF light illuminated       | OK |    |
| ABS light illuminated   | OK |      |                             |    |    |