

VEHICLE INSPECTION REPORT

FN17BRX

Daf LF 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	03/07/2017	VIN	XLRAEL3700L463392	Cab Type	DAY CAB
Year	2017	Body Style	Curtainside	Gearbox	AUTOMATIC
Mileage	424,241 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Electronic / Online	Rear Suspension	Air
Colour	WHITE	MOT Due	31/08/2026	Rear Doors	Barn

AD-BLUE, SURROUND CAMERA SYSTEM, FORKLIFT BRACKETS

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Not Thru Paint



3: Fog Lamp Surround os
Broken
Replace



4: Bonnet
Cracked
Replace



5: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



6: Fog Lamp Surround ns
Scuffed (Unpainted)
UpTo 100mm



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Door Mirror Assy nsf
Missing
Replace



9: Other
N/A
N/A



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Other
N/A
N/A



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



14: Other
N/A
N/A



15: Other
N/A
N/A



16: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK