

VEHICLE INSPECTION REPORT

DG14SYZ

Man TGL 12.180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 21/07/2014

Year 2014

Mileage 202,194 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN WMAN05ZZ0EY314568

Body Style Box Van

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

Rear Doors Roller

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4


OSO1


OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos



1: Fog Lamp Surrounds
Scuffed (Unpainted)
Up To 100mm



2: Headlamps
Missing
Replace



3: Wing nsf
Missing
Replace



4: Door Mirror Assy nsf
Missing
Replace



5: Other
N/A
N/A



6: Lamp nsr
Missing
Replace



7: Bumper Rear
Missing
Replace



8: Lamp osr
Missing
Replace



9: Number Plate Rear
Missing
Replace



10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Door Mirror Assy osf
Missing
Replace



12: Flasher Side Repeater os
Missing
Replace



13: Seat Base Cover osf
Holed
Over 3mm



14: Other
N/A
N/A



15: Handle Inner osf
Damaged
Replace



16: Handle Inner nsf
Damaged
Replace



17: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK