

VEHICLE INSPECTION REPORT

VT19UKF

Vauxhall Movano 2.3 CDTI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/06/2019

Year 2019

Mileage 56,682 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W0VMRY60XKB185135

Body Style Panel Van L3

CAP Clean £6,250.00

CAP Average £5,475.00

CAP Below £4,375.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Navigation system
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Cracked
Replace



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Wing nsf
Dented
Between 10mm + 30mm



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Other
N/A
N/A



10: Sill ns
Dented
Between 10mm + 30mm



11: Qtr Panel Moulding ns
Missing
Replace



12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



14: Door nsr
Scratched
UpTo 25mm Thru Paint



15: Door osr
Dented
Between 10mm + 30mm



16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Qtr Panel Moulding os
Missing
Replace



18: Qtr Panel osr
Dented
Between 10mm + 30mm



19: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm



20: Qtr Panel osr
Dented
With Paint Damage



21: Qtr Panel osr
Dented
With Paint Damage

22: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



23: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	Fault