

VEHICLE INSPECTION REPORT

BL68OVF

Iveco Eurocargo 180-250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/02/2019

VIN ZCFA71TJ702688733

Cab Type DAY CAB

Year 2019

Body Style Curtainside

Gearbox AUTOMATIC

Mileage 311,378 Km Warranted

Service history Yes

Axle Combi 4x2

Fuel Type Diesel

Service documents Electronic / Online

Rear Suspension Steel

Colour WHITE

MOT Due 28/02/2026

Rear Doors Barn

WARNING LIGHTS ON DASH FORKLIFT BRACKETS, WEIGH SYSTEM, SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Front TowEye Cvr
Missing
Replace



3: Other
N/A
N/A



4: Screen Front
Chipped
UpTo 10mm



5: Bonnet
Chipped
Multiple Chips



6: Door Mirror Assy nsf
Broken
Replace



7: Door Mirror Assy nsf
Broken
Replace



8: Wing nsf
Scratched
UpTo 25mm Not Thru Paint



9: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



13: Other
N/A
N/A



14: Air Vents osf
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK