

VEHICLE INSPECTION REPORT

LL19OES

Isuzu N75 190

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 19/07/2019

Year 2019

Mileage 264,349 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN JAANPR75KH7109985

Body Style Fridge Box

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

Rear Doors Barn

Tail Lift Tuckaway

GAH UNIT, STANDBY PLUG, SIDE LOAD DOOR, SEPARATOR


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Screen Front
Chipped
Over 10mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Cracked
Replace



6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Cracked
Replace



8: Door osf
Dented
With Paint Damage



9: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		