

VEHICLE INSPECTION REPORT

CK67DPE

Mercedes-Benz Sprinter 3.5 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/10/2017

Year 2017

Mileage 64,667 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9066332P537914

Body Style Panel Van LWB

MOT Due 30/10/2025

CAP Clean £8,100.00

CAP Average £6,875.00

CAP Below £5,225.00

Axle Combi 4x4

AD-BLUE, SIDE LOAD DOOR, TOW BAR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Cruise control
- Drivers airbag
- Digital radio
- Central locking
- Radio/CD Multichanger
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



3: Sill os
Chipped
Multiple Chips




4: Qtr Panel osr
Chipped
Multiple Chips



5: Qtr Panel osr
Chipped
Multiple Chips



6: Qtr Panel nsr
Chipped
Multiple Chips



7: Sill ns
Chipped
Multiple Chips



8: Bonnet
Dented
With Paint Damage

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK