

VEHICLE INSPECTION REPORT

PN71BVK

Fiat Doblo Work Up 1.6 MULTIJET 16V

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 22/11/2021

Year 2021

Mileage 105,730 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V35215

Body Style Dropside L2

MOT Due 09/09/2026

CAP Clean £5,625.00

CAP Average £5,125.00

CAP Below £4,300.00

Gearbox MANUAL

Gears 5

WARNING LIGHT ON DASH AD-BLUE

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Scratched
Over 25mm Not Thru Paint



3: Qtr Panel nsr
Dented
Over 30mm



4: Carpets Front
Holed
Over 3mm



5: Seat Base Cover osf
Holed
Over 3mm



6: Seat Back Cover osf
Torn
Over 3mm



7: Fascia Panel
Missing
Replace



8: Seat Base Cover nsf
Soiled
Heavy



9: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	Yes
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		